

Q



A□ □□□□□□□□10000□□□□□□

20□□□□□□□□

□□□□□□20□□□□

20□□□□□□□□□□□□□□□□


□□□□□□□□□□□□□□□□

□□□□□□□□□ □□□□□□□□□□□□□□□□□

□□□□

7

MOQ



Cupwind OEM / ODM



Wick Trimmer Cutter



Zinc Alloy Lid



Wooden Lid



TEST REPORT



8821087 0435
Page 3 of 4

TESTING FOR CA 85 LEAD & CADMIUM ON NON-FOOD / BEVERAGE GLASSWARE-EXTERIOR	
Sample Description: IRIDESCENT COATING CANDLE JAR	
Lot No: 10000	File No:
Order: 8821087 0435	Style:
Country of Origin: CHINA	Country of Destination: USA
Color: IRIDESCENT	SKU Number: ITEM: 8060
Brand name: CUPWIND®	
Re-test: Yes: No: ☒ X	Change Vendor: Yes: ☒ X No: ☐
Previous Report No: 17	

EXECUTIVE SUMMARY:	
Effectiveness of annealing	ASTM F2179-20 Sec. 4.2 (Mod): With a long-handled scrubber, scrub twice around the inside knuckle of the article. Then scratch an "X" across the entire inside bottom of the article. The article shall be held in a hot water bath at 71 ± 1 °C (160 ± 2 °F) for 15 minutes, then remove the article and examine each piece for fractures. That show no fractures. Report the number of fractures, if any, for each test. Modification: expanded scope to all other glass products in addition to candle containers. Shall not crack or break after tested per below: - prepare a cold water bath at 21 ± 1 °C (70 ± 2 °F); - prepare a hot bath at 71 ± 1 °C (160 ± 2 °F); - immerse the sample completely in the hot water bath and allow to soak for 5 min ± 15 s; - transfer the sample to the cold bath, and immerse for at least 30 s; - remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container through the second immersion. - the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to candle containers.
Normal shock	ASTM F2179-20 Sec. 4.2 (Mod): ASTM C149

Result Rating	Pass/Fail
M	PASS
M	FAIL

OVERALL RATING
PASS
FAIL
DATA
X

20

20

□□□□□□□□□□□□□□□□20□□□□□□□□□□□□

□□□□□□□□□□□□

