



□□□□□□□□□□10000□□□□□□□□

20□□□□□□□□□□□□□□

□□□□□□□□20□□□□□□

20□□□□□□□□□□□□□□□□□□□□

□□□□□□□□□□□□□□□□□□□□







本公司承接各類產品OEM、ODM業務

歡迎各界人士垂詢、洽談、參觀、指導

地址：廣東省深圳市龍崗區

電話：0755-12345678 9

TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD,
HENGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-0435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u>X</u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Commodity:	DESCENDANT	SKU Number:	11044-0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☒	Change Vendor:	Yes: ☒ No: ☐
Previous Report No.:	/		




Page 3 of 4

EXECUTIVE SUMMARY

Test content		Result Rating
Ca II L-Lead & Cadmium on non-food/beverage glassware inference		Mist/Past
Effectiveness of rinsing	AISTM F2799-03 Sec. 4.2 (MoE)	M PASS
	Wash a large open carafe or bottle twice from bottom to top with distilled water. Then invert the carafe/bottle upside down so the surface of the article. All surfaces are to be made using sufficient pressure to wet/purify the surface of the glass. Rinse the article with water at the same room temperature as the glass. Wait 15 minutes, then dry the vessel and examine each piece for fractures. That area is not broken. Report the number of fractures, if any, for each test.	
Thermal shock	AISTM F2799-03 Sec. 4.2 (Jettus) / ASTM C164	M PASS
	Modification: expanded scope to all other glass products in addition to carafe containers. The hot water that collects within the container prepares a cold-water bath at 21± 1°C (70°F ± 2°F). Prepare a hot bath at 71 ± 1°C (160 ± 2°F) immerse the sample completely in the hot water until it allows time to soak for 3 min ± 1 s. Remove the sample from the hot bath and transfer the sample to the cold bath and immerse for at least 30 s. Remove the sample from the cold bath and examine the sample for any cracking. Note: The hot water that collects within the container during the first immersion shall be retained in the container through the second immersion. The time of transfer from the hot bath to the cold bath shall be 15 ± 1 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to carafe containers.	

REMARK.

1. Not reviewed/protocol for test results in this report.



□ □

24/48/72/144 opp

[illegible]



Cupwind