



□□□□□□□□□□10000□□□□□□□□

20□□□□□□□□□□

□□□□□□□□20□□□□□□

20□□□□□□□□□□□□□□□□□□□□

□□□□□□□□□□□□□□□□□□□□

□□□□□□□□□□□□□□□□□□□□





ODM / OEM



歡迎各界人士垂詢、採購、OEM、ODM、
本公司承接各類產品設計、生產、銷售、
服務週到、價格公道、品質優良、
歡迎各界人士垂詢、採購、

TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD,
HONGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-0435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u>X</u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD /
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Commodity:	DESCENDANT	SKU Number:	11044-0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☒	Change Vendor:	Yes: ☒ No: ☐
Previous Report No.:	/		




Page 3 of 4

EXECUTIVE SUMMARY:

Test content		Result Rating
Ca II L-Leu & Cadmium on non-food/overage glassware inference		Most Pass
Effectiveness of rinsing	ASTM F2179-90 (Sec. 4.2.3.3.6)	M PASS
	Wash a large open carafe or bottle, scratch inside from the bottom knuckle of the article. Then position the article inside carafe to the bottom surface of the article. Add surfactant and be made using sufficient pressure to just penetrate the surface of the glass. Rinse the article with water at the same room temperature as the glass. Wait 15 minutes, then empty the water and examine each piece for fractures. That area is not fractured. Report the number of fractures, if any, for each test. Modification: expanded scope to all other glass products in addition to carafe containers.	
Thermal shock	ASTM F2179-90 (Sec. 4.2.3.3.6) & ASTM C149	M PASS
	Preparation: the test article is a glass carafe, prepare a cold water bath at 21 ± 1 °C (70 ± 2 °F). 1. prepare a hot bath at 77 ± 1 °C (160 ± 2 °F) 2. immerse the sample completely in the hot water and allow it to soak for 30 min ± 10 s 3. transfer the sample to the cold bath and immerse for at least 30 s 4. remove the sample from the cold bath and examine the sample for any cracking 5. the hot water that collects within the container during the first immersion shall be retained in the container through the first immersion 6. the time of transfer from the hot bath to the cold bath shall be 15 ± 5 s Modification: sampling procedure not followed and expanded scope to all other glass products in addition to carafe containers.	

REMARK.

1. Not reviewed/protocol for test results in this report.



□ □

24/ 48/ 72/ 144opp

[illegible]



Cupwind