



10000

20

20

20

20

20

20

□ □

A green glass candle jar with the words "HAVE DREAM" in gold lettering, sitting on a wooden base. The jar is filled with white wax and has a single wick. The background is a soft-focus indoor setting with a pink surface and a blue wall.

[illegible]



本公司承接各种玻璃器皿OEM/ODM业务

产品种类丰富，品质优良，价格公道，欢迎垂询。

地址：广东省佛山市顺德区北涌大街

电话：0757-28888888 13802222222

TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD
HONGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-0435

ATTN: EMMA ZOU
CC: emma@oupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u> X </u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWING COOPERATED FACILITY	P.O. No.:	/
Buyer:	SPS	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Color:	DESCENDANT	SKU Number:	110MAR 8090
Brand name:	CUPWING II		
Re-test:	Yes: ☐ No: ☒	Change Vendor:	Yes: ☐ No: ☒
Previous Report No.:	/		





185217087 04/25
Page 3 of 4

EXECUTIVE SUMMARY

Test content		Result/Rating	
CA 101 Lead & Cadmium on non-food/coverage glassware inference		Most Pass	
Effectiveness of rinsing	ASTM F2197-98 (Sec. 4.2.1 MoC)	With a large volume of water, scratch one corner around the inside tracks of the article. Then, swish an "S" shaped motion in water made bottom surface of the glass. As scratches are to be made using sufficient pressure, just penetrate the surface of the glass. Fill each article with water at the same room temperature as the glass. Wait 15 minutes, thoroughly the water and examine each piece for fractures. That since no fractures. Repeat the number of fractures, if any, for each test.	M PASS
Thermal shock	ASTM F2197-98 (Sec. 4.2.1.1 MoC) (A3) FM C149	Modification: expanded scope to all other glass products in addition to food containers. Shut out cracks or break after cooled as below: prepare a cold-water bath at 21 ± 1.1°C (70 ± 2°F). Prepare a hot bath at 77 ± 1.1°C (160 ± 2°F) enhance the sample completely in the hot bath and allow to soak for 3 min ± 1 s. Transfer the sample to the cold bath, and immerse for at least 30 s. Remove the sample from the cold bath and examine the sample for any cracking. Note: The hot water that collects within the container during the first immersion shall be retained in the container through the second immersion. The time of transfer from the hot bath to the cold bath shall be 15 s ± 1 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to food containers.	M PASS

REMARK:

3. Full services provided for test results in this report.





□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □

Cupwind