

300ml



10000

10000

20

20

20

[illegible]

□ □





ODM / OEM



專業承接各類金屬製品加工、OEM、ODM、來料加工、來圖加工、
承接各類金屬製品加工、承接各類金屬製品加工、承接各類金屬製品加工、
承接各類金屬製品加工、承接各類金屬製品加工、承接各類金屬製品加工、
[承接各類金屬製品加工、承接各類金屬製品加工、承接各類金屬製品加工、](#)



TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD
HONGKANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-6435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u>X</u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD
BEVERAGE GLASSWARE-EXTERIOR


Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Commodity:	DESCENDANT	SKU Number:	110MAR 0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☐	Change Vendor:	Yes: ☐ No: ☐
Previous Report No.:	/		

EXECUTIVE SUMMARY:

Test content		Result Rating		
CA 10 Label & Calculator on non-food/beverage glassware/enamel		Moist Heat		
Effectiveness of annealing	ASTM F2729-96 (Sec. 4.2.2 (M))	With a tungsten-carbide nozzle, scratch twice around the inside rim of the article. Then scratch an "X" across the inside rim of the outside surface of the article. All scratches are to be made using sufficient pressure to just penetrate the surface of the glass. Fill each article with water at the same room temperature as the glass. Wait 15 minutes. Then inspect the water and examine each piece for fractures. Each article is to fracture. Record the number of fractures, if any, for each test.	M	PA33
Thermal shock	ASTM F2729-96 (Sec. 4.2.2 (M) & 4.3.1 (C4))	Modification: expanded scope to all other glass products in addition to food containers. Soak test unit in hot water at 212 °F (100 °C) for 10 minutes. Then remove the test unit and prepare a cold-water bath at 21 ± 1 °C (70 ± 2 °F). Prepare a hot bath at 21 ± 1 °C (70 ± 2 °F) immerse the sample completely in the hot bath and allow it to soak for 15 ± 1 min. Transfer the sample to the cold bath and immerse for at least 30 s. Remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container throughout the immersion - the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s Modification: sampling procedure not followed and expanded scope to all other glass products in addition to food containers.	M	PA33

REMARK.

1. Not reviewed/protocol for test results in this report.

[illegible][illegible][illegible]



Cupwind