




□□□□□□□□10000□□□□□□□□

20

20

20



A collection of five surgical instruments, including a scalpel, a probe, a dissector, and two pairs of forceps, all with rose gold-colored handles, resting on a matching rose gold-colored tray.

[illegible]



Cupwind® OEM / ODM



Wick Trimmer Cutter



Zinc Alloy Lid



Wooden Lid



Neck



Stopper



Reed



Gift Box.



Gift Box



(9521)097-0435
Page 3 of 4

TEST REPORT

SHENZHEN JIERUIMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD,
HENGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (8521)097-0435

EXECUTIVE SUMMARY:

Test content	Result/Rating
CA 65 Lead & Cadmium on non-fluoropolymer glassware anterior	Meets/Pass

ASTM	EFTN:	EMMA ZOU	DATE IN:	APR 07, 2021
	CC:	emma.zou@astm.org	MOD. LOG IN:	
			DATE OUT:	APR 13, 2021
			REVISED DATE:	
			WORKING DAYS:	9
			PAGE:	2 OF 4

□□□ASTM

OVERALL RATING

PASS	<u> X </u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:	IRIDESCENT COATING CANDLE JAR		
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	IPSY	Style:	/
Country of Origin:	CHINA	Country of Destination:	USA
Color:	IRIDESCENT	SKU Number:	ITEM#: 8090
Brand name:	CUPWIND ®		
Seal:	Yes: ☐ No: ☒	Charge Vendor:	Yes: ☒ No: ☐
Requies Report No.:			

Effectiveness of airblasting	ASTM F2177-04 Sec. 4.2 (Mod.)	With a tungsten carbide probe, scratch across the inside lapped shoulder of the alloy. After each scratch, the probe must be held at an angle of 45° to the surface of the article. All scratches are to be made using sufficient pressure to just penetrate the surface of the glass. Place each scratch with water at the least in the candle containers as the glass. Wait 15 minutes, then dry the water and examine each sample for fractures. Shall show no fractures. Report the number of fractures, if any, for each test.	65	PASS
Thermal shock	ASTM F2177-04 Sec. 4.2 (Mod.) ASTM C149	Modification: expanded scope to all other glass products in addition to candle containers. Shall not crack or break after limited per below: - prepare a cold water bath at 7 ± 1 °C (32 ± 2 °F). - prepare a hot bath at 71 ± 1 °C (160 ± 2 °F) - Immerse the sample completely in the hot water bath and allow to soak for 5 min at 10 s. - transfer the sample to the cold bath, and immerse for at least 20 s. - remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container through the second immersion - the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s Modification: sampling procedure not followed and expanded scope to all other glass products in addition to candle containers.	M	PASS

REMARK:

1. No enclosed protocol for test results in this report



