

Ombre

[illegible]

□□□□□□□□ 14 □□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□ 2000 □□



□□□□

10000□□□□□□

20□□□□□□□□

20□□□□□□

20□□□□□□□□

Armani Zara□□□□□□□□

[□□□□□□ .](#)



Cupwind 專業生產 OEM 及 ODM

玻璃杯、啤酒杯、威士忌杯、葡萄酒杯、咖啡杯、

馬爹利杯、威士忌杯、威士忌杯

Cupwind 專業生產各種玻璃杯。



10

□ □

TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD
HENGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-6435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u> X </u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD /
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:		DESCEND COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Commodity:	DESCENDENT	SKU Number:	110MAR 0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☐	Change Vendor:	Yes: ☐ No: ☐
Previous Report No.:	/		

EXECUTIVE SUMMARY

Test content		Result Rating		
Ca II Laid a. Examine on non-food/beverage glassware surface		Moist Pass		
Effectiveness of rinsing	ASTM F2179-30 (Sec. 4.2.3 MoE)	Wash a large-area carafe surface, scratch once from the middle knuckle of the article. Then, pour water over the surface to remove bottom surface of the article. All scratches are to be made using sufficient pressure to just penetrate the surface of the glass.	M	PA35
		Wash the surface of the glass article with water at the same room temperature as the glass. Wait 15 minutes. Then, dry the water and examine each glass for fractures.		
		That area is not broken. Report the number of fractures, if any, for each test.		
Thermal shock	ASTM F2179-30 (Sec. 4.2.3 MoE) AS/NZS C349	Modification: expanded scope to all other glass products in addition to carafe containers. Preparation: a) break the carafe container; prepare a cold-water bath at 21 ± 1 °C (70 ± 2 °F); b) prepare a hot bath at 71 ± 1 °C (160 ± 2 °F); c) immerse the sample completely in the hot water and allow it to soak for 3 min ± 1 s; d) transfer the sample to the cold bath; and e) immerse for at least 30 s. Examination: a) remove the sample from the cold bath and examine the sample for any cracking; b) the hot water that collects within the container during the first immersion shall be retained in the container throughout the examination. The time of transfer from the hot bath to the cold bath shall be 15 s ± 5 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to carafe containers.	M	PA38


PREMARK.

4. Put unreviewed/preliminary test results in this report.

□□□□□

□□□□□□□□□□

□□□□□ opp □□□□□24 □/48 □/72 □/144 □□□□□□□□□□□□

[illegible]

□ □ □ □ □ □ □ □

Cupwind



Wick Trimmer Cutter



Zinc Alloy Lid



Wooden Lid



Neck



Stopper



Reed



Gift Box.



Gift Box