


□□□□□□□□□□□□□□□□

[illegible][illegible]



□□□□

10000□□□□□□

20□□□□□□

20□□□□

20□□□□□□

Armani Zara□□□□□□

.



Cupwind 專業製造各種 OEM 及 ODM

不銹鋼杯、鋁杯、塑膠杯、玻璃杯、陶瓷杯、紙杯、


各種杯類、杯蓋、杯托、杯架、

[Cupwind 專業製造各種杯類](#) 。









□□□□

□□□□□□□□□□□□□□□□□□□□□□□□□□□□

.

TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD,
HONGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-0435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u> X </u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD /
BEVERAGE GLASSWARE-EXTERIOR

Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Color:	RED/SCENT	SKU Number:	110MAR 0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☐	Change Vendor:	Yes: ☐ No: ☐
Previous Report No.:	/		



Page 3 of 4

EXECUTIVE SUMMARY

Test content		Result Rating		
CA 101 Lead & Cadmium on non-food/overage glassware interior		Moist Heat		
Effectiveness of annealing	ASTM F279-96 Sec. 4.2 (NAI)	With a tungsten-carbide wire, scratch once around the inside rim of the article. Then scribe an "X" across the inside bottom surface of the article. All scratches are to be made using sufficient pressure to just penetrate the surface of the glass. Fill article with water at the same room temperature as the glass. Wait 15 minutes. Remove the water and examine each piece for fractures. Each article is to fracture. Record the number of fractures, if any, for each test.	M	PA33
Thermal shock	ASTM F279-96 Sec. 4.2 (M2) A312M (14)	Modification: expanded scope to all other glass products in addition to jar-like containers. Soak test unit in hot water (180 °F) for 15 min. Prepare a cold-water bath at 21 ± 1 °C (70 ± 2 °F). Prepare a hot bath at 71 ± 1 °C (160 ± 2 °F). Immerse the sample completely in the hot bath and allow to soak for 15 min. Transfer the sample to the cold bath and immerse for at least 30 s. Remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container - the container shall be removed from the hot bath and the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s Modification: sampling procedure not followed and expanded scope to all other glass products in addition to jar-like containers.	M	PA33


REMARK.

1. Not reviewed/protocol for test results in this report.

□ □ □ □ □

[illegible]

000000 opp 00000024 0/48 0/72 0/144 0000000000000000

[illegible]

--	--	--	--	--	--	--	--

Cupwind



Wick Trimmer Cutter



Zinc Alloy Lid



Wooden Lid



Neck



Stopper



Reed



Gift Box.



Gift Box