



□□□□□□□□□□10000□□□□□□□□

20□□□□□□□□□□

□□□□□□□□20□□□□□□

20□□□□□□□□□□□□□□□□□□□□

□□□□□□□□□□□□□□□□□□□□

□□□□□□□□□□□□□□□□□□□□

[illegible]





8



歡迎各界人士垂詢、參觀、採購、OEM、ODM、

本公司承接各類珠寶首飾、金銀首飾、

珠寶首飾、金銀首飾、珠寶首飾、

[Cupwind](#)珠寶首飾、金銀首飾、珠寶首飾、



TEST REPORT

SHENZHEN JIERUMA TRADING CO., LTD
NO.415 RUNLIAN BUILDING, SHENZHU ROAD
HENGANG, 518115, SHENZHEN, CHINA

LAB LOCATION: SHENZHEN
LAB NUMBER: (852) 3087-6435

ATTN: EMMA ZOU
CC: emma@cupwind.com

DATE IN: APR 07, 2021
MOD. LOG IN: /
DATE OUT: APR 13, 2021
REVISED DATE: /
WORKING DAYS: 5
PAGE: 2 OF 4

OVERALL RATING	
PASS	<u>X</u>
FAIL	<u> </u>
DATA	<u> </u>

TESTING FOR
CA 65 LEAD & CADMIUM ON NON-FOOD
BEVERAGE GLASSWARE-EXTERIOR


Sample Description:		DESCENDANT COATING CANDLE JAR	
Manufacturer:	CUPWIND COOPERATED FACILITY	P.O. No.:	/
Buyer:	PRV	Style:	
Country of Origin:	CHINA	Country of Destination:	USA
Commodity Code:	RESIDENTIAL	SKU Number:	11044-0090
Brand Name:	CUPWIND®		
Re-test:	Yes: ☐ No: ☐	Change Vendor:	Yes: ☐ No: ☐
Previous Report No.:	/		

EXECUTIVE SUMMARY:

Test content		Result Rating		
CA 101 Lead & Cadmium on non-food/overage glassware interior		Moist Heat		
Effectiveness of annealing	ASTM F2197-96 Sec. 4.2 (NAI)	With a nitrogen candle source, transfer ions from the inside surface of the article. The annealing is "12" minutes at 1200°C inside bottom surface of the article. All samples are to be made using sufficient pressure to just penetrate the surface of the glass. Fill sample with water at the same room temperature as the glass. Wait 15 minutes. Remove the water and examine each piece for fractures. Each piece is to fracture. Report the number of fractures, if any, for each test.	M	PA33
Thermal shock	ASTM F2197-96 Sec. 4.2 (M2) / ASTM C149	Modification: expanded scope to all other glass products in addition to sample containers. Soak test sample in hot water (180-212°F) for 2 hours. Prepare a cold-water bath at 21°F ± 1°C (7°F ± 2°F). Transfer a hot sample at 21°F ± 1°C (7°F ± 2°F) immerse the sample completely in the cold water bath and allow to soak for 15 ± 1 minutes. Transfer the sample to the cold bath and immerse for at least 30 s. Remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container for the subsequent immersion. - the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to sample containers.	M	PA33

REMARK.

1. Not reviewed/protocol for test results in this report.

[illegible]

24 / 48 / 72 / 144 opp

[illegible]



Cupwind