

Candle Cloche Glasmaschinengepresst mit LuxusQualität

Q

Unsere Stärke?

EIN: 10000 Quadratmeter Dekorationswerkstatt.

20 verschiedene Dekorationsmaschinen.

20 Jahre Erfahrung im Dekorationsbereich.

20 stabile Glasfabriken unterstützen.

Weltweit bekannte Marken wie Armani Zara etc.

Cupwind ist reich an Erfahrung [Kerzenglocke Hersteller China](#) für viele Jahre.

Produktmerkmale

Diese Kerzenglocke wird durch maschinelles Pressen hergestellt und ist haltbarer als handgefertigte.

Es passt perfekt zu [...](#)

Die Glocke ist ein gutes Geschenk für Duftkerzenset, Hochzeit, Hauseinweihung, Geburtstagsgeschenk.





Wirkung des Prozesses

Cupwind akzeptiert kundenspezifisches OEM/ODM-Design.

Wir können Ihre eigene Form mit/ohne Markennamen erstellen.

Die Dekoration ist zum Sprühen, Galvanisieren, Metallic-Lackieren, Abziehbild, Heißprägen, Siebdruck, Sandstrahlen, Wassertransfer usw. erhältlich.



Wir bieten Kerzenzubehörsatz in Schwarz, Silber, Gold, Roségold, Bronze usw. an. Holzdeckel, das Material des Holzes ist in MDF, Kiefer, Bambus, Buche, Walnuss, Paulownia, Akazie, Gummibaumholz, Roteiche, Weißeiche, europäische Esche, Ahorn usw. Metalldeckel, das Material des Metalls ist in Zinn, Edelstahl, Zinklegierung, rostfreiem Eisen usw. erhältlich.

TEST REPORT

SHENZHEN BEIJING TRADING CO., LTD. LAB LOCATION: SHENZHEN
HENGSHAN, SHENZHEN, CHINA

EXECUTIVE SUMMARY:

Test Item	Standard	Result	Pass/Fail	
Endurance of annealing	ASTM F2159-20 (Sec. 4.2 (A)(i))	With a long-term annealing, scratch area around the inside knuckle of the article. Then scratch an "X" across the entire inside bottom surface of the article. All scratches go to be 1/16" (1.6mm) deep. After 15 minutes, immerse the article in a hot water bath at the same room temperature as the glass. Wait 15 minutes, then empty the water and examine each piece for fractures. Shall show no fractures. Report the number of fractures, if any, for each test.	0	PASS
Thermal shock	ASTM F2159-20 (Sec. 4.2 (A)(ii) / ASTM C-44)	Modification: expanded scope to all other glass products in addition to candle containers. Shall not crack or break after tested per below: - prepare a cold water bath at 21 ± 1 °C (70 ± 2 °F); - prepare a hot bath at 71 ± 1 °C (160 ± 2 °F); - immerse the sample completely in the hot water bath and allow to soak for 5 min ± 10 s; - transfer the sample to the cold bath, and immerse for at least 30 s; - remove the sample from the cold bath and examine the sample for any cracking. Note: - the hot water that collects within the container during the first immersion shall be retained in the container through the second immersion. - the time of transfer from the hot bath to the cold bath shall be 15 ± 1 s. Modification: sampling procedure not followed and expanded scope to all other glass products in addition to candle containers.	0	PASS

OVERALL RATING: PASS

TESTING FOR: CARS LEAD & CADMIUM ON NON-FOOD / BEVERAGE GLASSWARE-EXTERIOR

Sample Description: IRIDESCENT COATING CANDLE JAR
Manufacturer: CUPWIND COOPERATED FACILITY
Buyer: SPY
Country of Origin: CHINA
Exporting Destination: USA
Brand name: CUPWIND
Re-test: Yes: No: X
Charge Vendor: Yes: X No: ☐

REMARK: 1. No enclosed protocol for test results in this report.

Alle Bestellungen des Kerzenglases aus Glas werden von Dritten getestet.

Normalerweise gehen wir mit Cali 65 Pro-Tests, ASTM-Tests (Annealing and Thermal Shock), Blei- und Cadmium-Tests.

Cupwind hat eine 10000 Quadratmeter große Dekorationswerkstatt.

20 verschiedene Dekorationsmaschinen.

20 Jahre Erfahrung im Dekorationsbereich.

Über 20 stabile Glasfabriken, die mit verschiedenen Glasgefäßen unterstützt werden.

Verpackungs- und Palettenprozess

Wellpappe mit Trennwänden, sicher für den internationalen Versand.

Kundenspezifische E-PA benutzbar, Softbox-Anforderungen sind akzeptabel.

